

Crystal Cap Cleaners Inc.
4401 Corporate Drive,
Burlington, Ont.



Daimler AG
Mercedes-Benz Bremen Plant
28190 Bremen
Germany

Dear Mr. Hills,

We finally installed the cleaners in Line 2 Base coat and are pleased to report the following results as per your request.

12 days reporting cycle	Before July 12 2010	After CCC install
No. of bodies per shift	370	410
Average no. stops for manual clean	24	4
Yield, first run	92%	96%

There was a very good response from our health and safety boss that keeping the operators out of the booth was a very positive move in our process.

The cleaning was achieved within the colour change cycle time and the cup and shroud were actually cleaner than when cleaned manually.

It took us a full morning to balance the air pressures between the impeller air pressure and the atomizer pressure and achieve the cleaning of the shape air holes without having contamination migrating into the turbine.

Please thank Mr. White for all his assistance in the initial set up and thank you for providing the cleaners at no cost, we will have no problems in allocating the funds for purchasing the units for both lines as the pay back is very fast.

Yours sincerely,

A handwritten signature in black ink, appearing to read "Walter Schneider".

Walter Schneider
Process Engineer
Paint shop